Performance of Thermal Barrier Coatings in High Heat Flux Environments

Robert A. Miller Lewis Research Center Cleveland, Ohio

and

Christopher C. Berndt Cleveland State University Cleveland, Ohio

Prepared for the International Conference on Metallurgical Coatings sponsored by the American Vacuum Society San Diego, California, April 9-13, 1984



PERFORMANCE OF THERMAL BARRIER COATINGS IN HIGH HEAT FLUX ENVIRONMENTS

Robert A. Miller
National Aeronautics and Space Administration
Lewis Research Center
Cleveland, Ohio 44135

and

Christopher C. Berndt*
Cleveland State University
Cleveland, Ohio 44115

SUMMARY

Thermal barrier coatings were exposed to the high temperature and high heat flux produced by a 30 kW plasma torch. Analysis of the specimen heating rates indicates that the temperature drop across the thickness of the 0.038 cm ceramic layer was about 1100° C after 0.5 sec in the flame. An as-sprayed $Zr0_2-8\%Y_20_3$ specimens survived 3000 of the 0.5 sec cycles with failing. Surface spalling was observed when 2.5 sec cycles were employed but this was attributed to uneven heating caused by surface roughness. This surface spalling was prevented by smoothing the surface with silicon carbide paper or by laser glazing. A coated specimen with no surface modification but which was heat treated in argon also did not surface spall. Heat treatment in air led to spalling in as early as 1 cycle from heating stresses. Failures at edges were investigated and shown to be a minor source of concern. Ceramic coatings formed from $Zr0_2-12\%Y_20_3$ or $Zr0_2-20\%Y_20_3$ were shown to be unsuited for use under the high heat flux conditions of this study.

INTRODUCTION

A thermal barrier coating system with sufficient durability to survive on airfoil surfaces in a moderately high heat flux, moderately high temperature, research gas turbine engine was first reported in the mid 1970's (refs. 1 and 2). However, this early thermal barrier coating system, which consisted of a layer of air plasma sprayed $ZrO_2-12\%Y_2O_3$ applied directly over a layer of air plasma sprayed NiCrAlY bond coat, was unable to survive in an advanced research gas turbine engine (ref. 3). Thermal barrier coatings have now been improved to the extent that they are used in revenue service on vane platforms in advanced, commercial gas turbine engines (ref. 4). Among the more significant advances responsible for this current success is the discovery that a $ZrO_2-8\%Y_2O_3$ coating is much more durable than the earlier, $ZrO_2-12\%Y_2O_3$ version (ref. 5). Possible reasons for this are discussed in reference 6.

In the future, advanced engines operating at heat fluxes greater than those characteristic of current engines will require thermal barrier coatings for protecting airfoil surfaces. The testing which has led to advances in

^{*}Fellow of the Joint Institute for Aerospace Propulsion and Power.

coating performance has been conducted in the low to moderate heat flux environment of furnaces and burner rigs. The initiation of coating failure in such rigs is associated with thermal expansion mismatch strain encountered on cooling and with time-at-temperature effects such as bond coat oxidation and plastic deformation (ref. 7). Strains encountered on heating in such rigs are not severe enough to initiate coating failure (ref. 7). It is not yet known whether strains encountered on heating in a gas turbine engine are severe enough to contribute to failure initiation.

Therefore, testing procedures must be devised that allow determination of when the thermal loads developed on rapid heating become severe enough to initiate coating failure. This information may then be used to guide the processing of coatings for improved tolerance to such loads. In this study, a commercial plasma torch has been used as a high heat flux source. Various plasma sprayed zirconia-yttria thermal barrier coating systems were exposed in this rig and the response of these coatings to the high heat flux environment generated was characterized.

The plasma torch rig used for this study is intended to serve as an interim rig until a high pressure burner rig and a rocket engine test rig dedicated to materials research are available at the Lewis Research Center. Precedents for this type of test exist (refs. 8 and 9). The torch is relatively simple and inexpensive to operate. Possible disadvantages of this rig include the small flame diameter and the extremely high gas temperature attained.

EXPERIMENTAL

A schematic diagram of the test rig is shown in figure 1. The plasma torch shown is operated at a power level of 30 kW. The nitrogen arc gas flow rate was 2800 1/hr. The distance from the exit nozzle of the torch to the specimen is 4.4 cm. Specimens are held in the flame for either 0.5, 2.5, or 5.0 sec cycles followed by 30, 75, or 120 sec of forced air cooling. An additional 0.50 sec is required for the specimen to move between the cooling position and the heating position, and specimen heating begins before the specimens are fully in the heating position. Therefore effective heating times may be taken as 0.1 sec longer than the nominal times.

Test specimens were solid 1.3 cm diameter superalloy rods. Usually the alloy was René 41. The thermal barrier coatings consisted of 0.013 cm of bond coat which was usually Ni-14%Cr-14%Al-0.1 Zr under a 0.038 cm layer of plasma sprayed zirconia-yttria ceramic. The yttria level was usually 8 wt %; 12 and 20 wt % yttria ceramics were also investigated. Sintered starting powders were used for the 8 and 12% yttria compositions while a nonreacted composite powder was used for the 20% yttria composition.

Specimens were tested in the as-sprayed condition, after heat treating in air or in argon, and after surface treatment by smoothing with silicon carbide paper or laser glazing. The laser glazed specimens were only available as hollow, cylindrical specimens.

RESULTS AND DISCUSSION

Characterization of the Plasma Flame and of Specimen Heating Rates

The apparent gas temperature of a 30 kW nitrogen plasma at a distance of 4.4 cm from the nozzle was determined through measurement of the power required to melt small samples of Al_2O_3 or $ZrO_2-6\%Y_2O_3$. A plot of the logarithm of the known melting (or solidus) points versus the logarithm of the power required to melt the samples gives a line of slope equal to 1/4 as shown in figure 2. This slope arises from the Stefan-Blotzman relationship and is consistent with the assumption that heat is transferred from the cathode of the plasma torch to the plasma by radiation (ref. 10) and from the gas to the samples by convection and conduction (ref. 11).

Extrapolation of the line in figure 2 to 30 kW yields an apparent flame temperature of 3000° C. The actual gas temperature may differ somewhat since heat will be lost from the sample by radiation or gained by aerodynamic heating.

The heat transfer coefficient from the gas to the sample was measured to be $0.2~\rm W~cm^{-2}~^{\circ}C^{-1}$. A button calorimeter similar to the ones described in references 9 and 12 but of simplified design was used for this determination. The heat transfer coefficient and the apparent gas temperature were used to calculate the temperature distributions in the coated specimens as a function of time. A one-dimensional finite difference model was used for this calculation. The computer code employed was taken from reference 13 (the reader is cautioned that there are several errors in the FORTRAN listing given in ref. 13). Values for the thermal conductivities and heat capacities of the bond coat and ceramic were taken from reference 14. Values pertaining to 500° C were used.

The calculated heating rates at the ceramic surface and at the interface with the bond coat are presented in figure 3. An initial response of 0.1 sec was assumed as explained in the experimental section. Temperatures measured by a thermocouple centered 0.076 cm below the interface are also shown on the plot. These temperatures appear to be consistent with the calculated interface temperatures. The time at which the surface of the specimen was observed to be fully glowing in a 1/8000 sec photograph is also indicated on the plot. This time corresponds to a calculated surface temperature of about 1100° C, and the observation of glowing at this temperature seem plausible in view of the very short exposure time.

A very large ΔT between the surface and the interface has been achieved in this test. At 0.5 sec this difference is almost 1100° C. As shown in the figure this is much greater than the ΔT calculated for a 0.018 cm ceramic coating in a research gas turbine engine during the take-off portion of the cycle (ref. 3) and is greater still than the ΔT for a 0.038 cm coating in a Mach 0.3 burner rig (ref. 15).

One can calculate the compressive thermal strain at the surface of the ceramic relative to the mean thermal strain in the ceramic from the expression (ref. 16)

$$\varepsilon = \alpha \left(\overline{T} - T_{surf} \right) \tag{1}$$

where α is the thermal expansion coefficient of the ceramic -- about $10x10^{-6}$ (ref. 17) -- and \overline{T} is the mean temperature in the ceramic layer. The values of the relative strain calculated from expression 3 are -0.57, -0.48, and -0.42% at 0.5, 2.5, and 5.0 sec, respectively. One may note that surface compressive strains are larger after 0.5 sec than after 2.5 or 5.0 sec. A complete calculation of strain would include ceramic/metal thermal expansion mismatch strains and residual stress.

From the above analysis it is apparent that the thermal loads imposed on coated specimens in this plasma torch rig are much more severe than those to be expected in a gas turbine engine.

Response of Thermal Barrier Coating to High Heat Flux

The results of this investigation are displayed in figure 4. In this figure the composition of the ceramic, the pretreatment given to the specimen, the duration of the heat cycle, and the type of failure observed, if any, are given. The total number of cycles is represented by the length of the bar. A pointed arrow indicates no failure. The test was terminated if no failure was observed after 1000 0.5 sec cycles or after 100 2.5 sec cycles. An exception was case A which ran for 3000 cycles before removing from the test.

Case A pertains to as-sprayed ZrO₂-8%Y₂O₃ ceramic and the lack of failure after 3000 cycles is quite encouraging. When the cycle duration was increased to 2.5 or 5.0 sec, cases B and C, respectively, then surface spalling was observed after 15 cycles. This surface spalling was observed even though the relative surface strains at the end of the 2.5 sec cycles exceeded those at the end of the 0.5 sec cycles. A photograph of the surface of the specimen from case B is shown in figure 5. In case C the surface spalling was accompanied by surface melting even though the calculated temperature after 5 sec (fig. 3) was about 800° C lower than the melting point of the ceramic. This indicates that there must be local hot spots on the rough surface. High speed photography indicated that some regions of the rough specimen began to glow almost 0.1 sec before the surface came to a full glow. This local glowing occurs even before the specimen comes fully into position. Therefore one can expect that there will be areas of severe local stress concentration at the rough surface of a specimen exposed to these very high temperatures.

Smoothing the coating surface with silicon carbide paper, case D and figure 6, prevents surface spalling. This smoothing reduced the measured roughness from about 10 μ (AA) to about 4 μ (AA). A laser glazed specimen did not surface spall after 15 2.5 sec cycles, case F. The results for the laser glazed specimen must be considered preliminary because the only specimens available at the time of this study were on hollow substrates which had previously been tested to failure in the hot zone region in a burner rig test. Regions away from the failure area were exposed in the plasma torch rig. The specimen in case F actually spalled after 20 cycles. However, at the present time it is not known whether this may have been due to some factor such as overheating of the hollow specimen. The laser glazed specimen in case E survived 1000 0.5 sec cycles but it cracked and eventually spalled in the unglazed region near the upper edge as shown in figure 7. It should be noted that the cracks emanating from the unglazed areas dissipate once they reach the mudcracked, laser glazed region. Thus, even though the results on laser glazed

specimens are preliminary, this process (which is discussed in ref. 18) is promising for high heat flux applications.

Since spalling had been observed at the edge of the hollow specimen in case E, the response of a solid specimen to heating at an edge was investigated. No edge effect spalling was observed after 1000 0.5 sec cycles, case G. However, a minor amount of edge spalling was observed after 3 of the 2.5 sec cycles, case H and figure 8.

Case I indicates that there is a strong correlation between oxidation and spalling on heating. A specimen which had received a relatively severe oxidative heat treatment -- 20 hr at 1200° C in air -- spalled in the first cycle in one test (fig. 9) and in the third cycle in another test. Presumably the ceramic had been weakened near the interface with the bond coat as a result of strains induced by the formation of an oxide layer at the interface combined with thermal expansion mismatch strains encountered on cooling. A specimen heated for 20 hr at 1250° C in an inert environment, case J and fig. 10, did not spall and did not even surface spall after 100 2.5 sec cycles.

A $ZrO_2-12\%Y_2O_3$ coated specimen was severely microcracked after 250 0.5 seccycles, case K. This specimen was subsequently destroyed when it became stuck in the heating position. Another $ZrO_2-12\%Y_2O_3$ specimen began to spall after 7 2.5 sec cycles, case L. Three $ZrO_2-20\%Y_2O_3$ specimens, case M, spalled during the first cycle.

CONCLUDING REMARKS

The above results show that thermal barrier coatings having a ceramic layer based on $Zr0_2-8\%Y_20_3$ can withstand thermal strains greatly in excess of those expected in a gas turbine engine. Surface spalling associated with extremely high gas temperatures was encountered but this could be prevented by smoothing the surface with silicon carbide paper. Heat treating in an inert environment may also prevent surface spalling. Results on laser glazed specimens are preliminary, but it appears that glazed specimens also withstand heating stresses quite well.

Oxidation appears to induce spalling on heating. Thus oxidation has been implicated as a key factor in coating failure in both the heating mode in high heat flux plasma torch tests and in the cooling mode in moderate heat flux burner rig tests. This observation is cause for concern regarding the use of coatings for long periods of time in a high heat flux environment. Therefore, the effects of oxidation require further investigation. Spalling at an edge may be a minor concern. Coatings formed from $ZrO_2-12\%Y_2O_3$ or $ZrO_2-20\%Y_2O_3$ were unsuited for use at the high heat flux generated by the plasma torch.

REFERENCES

- 1. S. Stecura, "Two-Layer Thermal Barrier Coating for Turbine Airfoils Furnace and Burner Rig Test Results." NASA TM-X-3425. Sept. 1976.
- 2. C. H. Liebert, R. E. Jacobs, S. Stecura and C. R. Morse, "Durability of Zirconia Thermal-Barrier Ceramic Coatings on Air-Cooled Turbine Blades in Cyclic Jet Engine Operation," NASA TM-X-3410, Sept. 1976.

- 3. W. R. Sevcik and B. L. Stoner, PWA-5590 (Pratt and Whitney Aircraft Group, East Hartford, CT, 1978) NASA CR-135360.
- 4. K. D. Sevcik and B. L. Stoner, PWA-5590 (Pratt and Whitney Aircraft Group, East Hartford, CT, 1982) NASA CR-167964.
- 5. S. Stecura, "Effects of Compositional Changes on the Performance of a Thermal Barrier Coating System Yttria-Stabilized Zirconia Coatings on Gas Turbine Engine Blades," NASA TM-78976.
- R. A. Miller, R. G. Garlick and J. L. Smialek, Am. Ceram. Soc. Bull. <u>62</u>, 1355-1358, (1983).
- 7. R. A. Miller and C. E. Lowell, Thin Solid Films, 95, 265-273, (1982).
- 8. A. N. Current, S. J. Grisaffe and K. C. Wycoff, "Hydrogen Plasma Tests of Some Insulating Coating Systems for the Nuclear Rocket Thrust Chamber," (1982).
- 9. H. E. Smith and J. C. Wurst, "The Evaluaton of High Temperature Materials Systems with an Arc-Plasma-Jet," ASD-TDR-623-655, July 1962.
- 10. C. W. Chang and J. Szekely, J. Metals, 34, no. 2, 57-64, (1982).
 11. M. Ushio, J. Szekely, and C. W. Chang, Ironmaking Steelmaking, 8,
- 11. M. Ushio, J. Szekely, and C. W. Chang, Ironmaking Steelmaking, 8, 279-286, (1981).
- 12. J. Huminik, <u>High-Temperature Inorganic Coatings</u> (Reinhold, New York, 1963. 197-198.)
- 13. H. Schenck, <u>FORTRAN Methods in Heat Flow</u> (Ronald Press, New York, 1963, pp. 93-106.)
- 14. P. A. Siemers and W. B. Hillig, SRD-81-083 (General Electric Co., St. Petersburg, FL, 1981) NASA CR-165351.
- 15. G. McDonald and R. C. Hendricks, Thin Solid Films, 73, 491-496, (1980).
- S. S. Manson, <u>Thermal Stress and Low-Cycle Fatigue</u>, (McGraw-Hill, New York, 1966, p. 277.)
- 17. C. C. Berndt and H. Herman, Ceram. Eng. Sci. Proc., 4, 792-801, (1983).
- 18. I. Zaplatynsky, Thin Solid Films, 95, 275-284, (1982).




Figure 1. - Schematic diagram of plasma torch test rig.




Figure 2. - Plasma torch arc power versus apparent gas temperature.




Figure 3. - Calculated heating rates at ceramic layer surface and interface with bond coat for a 0, 038 cm ceramic coating in the plasma torch (——) or Mach 0, 3 burner rig (----) or a 0, 018 cm ceramic coating in a research gas turbine engine (———).




Figure 4. - Response of 0, 038 cm zirconia-yttria coatings to 0, 5, 2, 5, and 5, 0 second exposure cycles in a 30 kW (3000⁰ C) plasma flame.



Figure 5. - As-sprayed ZrO₂-8% $\rm Y_2O_3$ specimen after 15 2.5 second cycles (case B) in a 30 kW plasma flame.

Figure 6. - Smoothed ArO₂-8% Y₂O₃ specimen after 100 2.5 second cycles (case D) in a 30 kW plasma flame.




Figure 8. - Edge of Zr02-8% $\rm Y_20_3$ specimen after 3 cycles (case H) in a 30 kW plasma flame.




Figure 7. - Laser glazed ZrO_2 -8% Y_2O_3 specimen after first 25 of a total of 1000 0,5 second cycles (case E) in a 30 kW plasma flame. The hot zone is near the bottom, Edge effect cracking of the coating on the hollow specimen in the unglazed region near the top.




Figure 9. - Preoxidized ArO₂-8% $\rm Y_2O_3$ specimen (20 hr at 1200 $_0$ C main) after 10.5 second cycle (case I) in a 30 kW plasma flame.



Figure 10. - Argon heat treated ZrO₂-8% Y₂O₃ specimen (20 hr at 1250⁰ C) after 100 2.5 second cycles (case J) in a 30 kW plasma flame.

	T			
1. Report No.	2. Government Accession	on No.	3. Recipient's Catalog N	0.
NASA TM-83663 4. Title and Subtitle			5. Report Date	
4. Title and Subtitle			3. Neport Date	
Performance of Thermal Barrier Coatings in High				
Heat Flux Environments			6. Performing Organization Code 505-33-1A	
			505-35-1A	
7. Author(s)			8. Performing Organization Report No.	
Robert A. Miller and Christopher C. Berndt			E-2010	
		11	10. Work Unit No.	
9. Performing Organization Name and Address		1. Contract or Grant No.		
National Aeronautics and Space Administration Lewis Research Center				
Cleveland, Ohio 44135		-	13. Type of Report and Period Covered	
12. Sponsoring Agency Name and Address			Technical Memorandum	
National Aeronautics and Space Administration Washington, D.C. 20546			14. Sponsoring Agency Code	
15. Supplementary Notes				
Robert A. Miller, Lewis Research Center; Christopher C. Berndt, Cleveland State				
University, Joint Institute for Aerospace Propulsion and Power, Cleveland, Ohio 44115. Prepared for the International Conference on Metallurgical Coatings				
sponsored by the American Vacuum Society, San Diego, California, April 9-13, 1984.				
46. Abatrasi				
16. Abstract				
Thermal barrier coatings were exposed to the high temperature and high heat flux produced by a 30 kW plasma torch. Analysis of the specimen heating rates indi-				
cates that the temperature drop across the thickness of the 0.038 cm ceramic layer				
was about 1100° C after 0.5 sec in the flame. An as-sprayed ZrO ₂ -8%Y ₂ O ₃ speci-				
mens survived 3000 of the 0.5 sec cycles with failing. Surface spalling was ob-				
served when 2.5 sec cycles were employed but this was attributed to uneven heating				
caused by surface roughness. This surface spalling was prevented by smoothing the surface with silicon carbide paper or by laser glazing. A coated specimen with no				
surface modification but which was heat treated in argon also did not surface				
spall. Heat treatment in air led to spalling in as early as 1 cycle from heating				
stresses. Failures at edges were investigated and shown to be a minor source of				
concern. Ceramic coatings formed from ZrO ₂ -12%Y ₂ O ₃ or ZrO ₂ -20%Y ₂ O ₃ were shown				
to be unsuited for use under the high heat flux conditions of this study.				
				-
17. Key Words (Suggested by Author(s)) 18. Distribution Statement				
Thermal barrier coatings; High heat flux;		Unclassified - unlimited		
Plasma torch; Laser glazing; Oxidation		STAR Category 26		
19. Security Classif. (of this report) 20). Security Classif. (of this	l page)	21. No. of pages	22. Price*
Unclassified	Unclassi			

National Aeronautics and Space Administration

Washington, D.C. 20546

Official Business
Penalty for Private Use, \$300

SPECIAL FOURTH CLASS MAIL BOOK





Postage and Fees Paid National Aeronautics and Space Administration NASA-451

NNSN

POSTMASTER:

If Undeliverable (Section 15% Postal Manual) Do Not Return